

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6A plotting all of the measurement points in the mapping measurement














Fig. 6B example of expressing as contour an orientation distribution function to specific index.










Fig. 10







Fig. 12B

Fig. 12C

Fig. 12D

Fig. 12E

Fig. 12F






Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17A




Fig. 17 B




Fig. 18






Fig. 19






Fig. 21




Fig. 22A




Fig. 22B




Fig. 22C




Fig. 22D




Fig. 22E

Fig. 23A




Fig. 23B






Fig. 23C










Fig. 26 A





Fig. 26 B